



Photograph from the Wilfred N. Ball Collection. Copy courtesy of Karl V. Steinbrugge.
FIGURE 1.—Damage to downtown Compton, Calif., 40 km (25 mi) from the epicenter of the 1933 Long Beach earthquake. This damage is typical of the effects of a moderate to large (magnitude 6-8) earthquake on old, unreinforced brick masonry. Note that the second story wall has collapsed and the roof is supported only by the interior partition (nonbearing) walls.



Photograph by the Los Angeles Times. Copy courtesy of Karl V. Steinbrugge.
FIGURE 2.—Damage to Jefferson Junior High School from the 1933 Long Beach earthquake. This earthquake caused the destruction of many public schools and caused the California legislature to pass the Field Act, mandating that all new public schools in the state be built to resist earthquake vibrations. The effectiveness of this legislation has been demonstrated by the superior performance of post-1933 schools in California earthquakes (Richter, 1958).



Photograph by Bureau of Land Management. Copy courtesy of Karl V. Steinbrugge.
FIGURE 10.—Damage to the Penny Building in Anchorage during the 1964 Alaska earthquake. This building, constructed in 1962, was supported by bearing walls on all (or parts of all) sides except the north; this photograph shows the northeast corner. Lack of shear walls above the first story along the north side gave the building a U-shaped shear-wall bracing system, which is especially susceptible to torsional (twisting or rotational) forces. An eyewitness described the Penny Building as twisting, with movement along the second floor construction joints (Steinbrugge, Manning, and Degenskolb, 1967).




Photograph from the NOAA National Geophysical Data Center.
FIGURE 11.—Slump that destroyed a section of road during the Hebgen Lake, Mont., earthquake of 1959 (magnitude 7.1).




Photograph by J. K. Killers. Copy from the NOAA National Geophysical Data Center.
FIGURE 12.—Sand blow created during the 1886 Charleston, S.C., earthquake. Sand blows are a result of liquefaction, a phenomenon that occurred over a wide area during the 1811-1812 New Madrid earthquakes. Liquefaction is the sudden transformation of a loose, silty soil into a fluid, as a result of repeated vibrations such as those produced by a large earthquake. Earthquake shaking can pump or squeeze the fluid from a liquefied layer up through cracks in the overlying material, producing sand blows.



Photograph from NOAA National Geophysical Data Center.
FIGURE 13.—Apartment buildings that tilted due to liquefaction at the base of the buildings during the 1964 earthquake in Niigata, Japan (magnitude 7.5). The buildings remained intact and the people inside escaped unharmd (Kawasumi, 1968).




Photograph from the U.S. Geological Survey Photographic Library.
FIGURE 14.—Turnagain Heights slide after the 1964 Alaska earthquake. In this case, and in figures 15 and 16, upper strata in a liquefied lower layer known as the Bootlegger Cove Clay. If you look at this picture carefully you can see the houses on the blocks of earth that dropped.



Photograph from the U.S. Geological Survey Photographic Library.
FIGURE 15.—School partly on a dropped block, or graben, on the Government Hill slide in Anchorage in 1964.



Photograph by the U.S. Army. Copy from the U.S. Geological Survey Photographic Library.
FIGURE 16.—Streets that collapsed in downtown Anchorage along the Fourth Avenue slide during the 1964 Alaska earthquake.



Photograph from the U.S. Geological Survey Photographic Library.
FIGURE 17.—Lower Van Norman Dam after the 1971 San Fernando earthquake. This was an hydraulic-fill dam built in 1918. A massive slide in the dam's earthfill embankment, possibly due to liquefaction, dislodged a major segment of the embankment along with its concrete lining and crest. They were deposited on the reservoir floor. The rupture surface was only 1.5 m (5 ft) above water level. It had the dam on the brink of failure. The Van Norman Dam held, although 80,000 people living below it had to be evacuated for four days while the reservoir water level was being lowered (Youd and Olsen, 1971). Had the magnitude of the earthquake been a little larger, and the vibrations continued for a few more cycles, the dam might well have failed.

INTERIOR—GEOLOGICAL SURVEY, RESTON, VIRGINIA—UNPUBLISHED 1990


For sale by U.S. Geological Survey Map Distribution, Box 25286, Federal Center, Denver, CO 80225



Photograph by J. K. Killers. Copy from the U.S. Geological Survey Photographic Library.
FIGURE 3.—Street in Charleston, S.C., after the 1886 earthquake (estimated magnitude $m_b=6.8-7.1$; Bollinger, 1977). Note that although some of the buildings have collapsed, others are relatively undamaged. There are even two tall chimneys still standing on the right.



Photograph from the U.S. Geological Survey Photographic Library.
FIGURE 5.—Highway overpass that collapsed during the 1971 San Fernando, Calif., earthquake (magnitude $M_w=6.5$), and blocked an interstate highway, several other roads, and the main lines of the Southern Pacific Railroad (Youd and Olsen, 1971).



Photograph by the Los Angeles Times. Copy courtesy of Karl V. Steinbrugge. Used by permission of the Times.
FIGURE 7.—Veterans Hospital near Olive View, Calif., which collapsed during the 1971 San Fernando earthquake killing 47 people (Olson, 1973). This reinforced concrete building was constructed in 1925 and not designed to be earthquake resistant (Jolani, 1973). Contrary to this building with the earthquake-resistant Olive View Hospital, where the structure remained standing and people escaped, even though the columns failed in the lower stories.




Photograph by Ward Wells. Copy courtesy of Karl V. Steinbrugge.
FIGURE 8.—Damage to the Mount McKinley Apartment Building, 120 km (75 mi) west of the epicenter of the 1964 Alaska earthquake (magnitude $M_w=6.3$). This building was one of two virtually identical buildings in Anchorage that were almost identically damaged. One of the piers (white vertical parts of the walls between the windows) on the north end of the building (the end facing the viewer in both figs. 8 and 9) failed in vertical parts at the third floor due to bending of the attached floor slab at that level. The spindly walls (wall spaces above and below the windows), being thinner and weaker than the piers, show the typical earthquake X-cracking or shear-cracking pattern on all four sides of the building. The cantilever spanned walls on the corners were cracked horizontally where construction joints between floors separated. This building was constructed according to building codes in use in the early 1950's. The floors were supported by the outside reinforced concrete bearing and shear walls and by the reinforced concrete walls in the elevator and stair cores near the center of the building. Shear forces caused by the earthquake were transmitted from the upper floor to the foundation via the right roof and floor diaphragms to the bearing walls (Steinbrugge, Manning, and Degenskolb, 1967).

FIGURE 9.—Close-up view of the part of figure 8 indicated by the rectangle, showing the failure of the pier at the third floor level, cracking at each floor level at the corners of the building, and X-cracking.



Photograph by Arnold Genthe. Copy courtesy of Karl V. Steinbrugge.
FIGURE 4.—San Francisco after the earthquake of 1906 (magnitude 8.3). Note that many of the visible buildings are not seriously damaged. Much of the damage in 1906 was caused by the fire rather than the ground shaking (although the lack of water with which to fight the fire resulted from the mains broken by the shaking). In the photograph, note from the left, an intact wood-frame building, two masonry buildings (the first has two collapsed chimneys), more buildings standing in the distance, and the fire several blocks away. From the right, notice cracks below the second story window of the first building, the unreinforced brick front of the second building collapsed above the first floor level and its debris scattered across the sidewalk and street, other buildings on the right that seem relatively intact.



Photograph from the U.S. Geological Survey Photographic Library.
FIGURE 6.—Olive View Hospital, 10 km (6 mi) from the epicenter of the 1971 San Fernando earthquake. The hospital was new and complied with the 1962 Los Angeles County building code, but its actual ground motion at Olive View greatly exceeded the code levels. The hospital was only 5 km from the Pacoima Dam site where a horizontal ground acceleration of $0.25g$ (g is the acceleration caused by the Earth's gravitational pull) was recorded. The lower two stories of the hospital had beam and column rigid joints that made the building act as a single unit. The lower two stories of the hospital had beam and column rigid joints that made the building act as a single unit. The lower two stories of the hospital had beam and column rigid joints that made the building act as a single unit.



Photograph courtesy of Karl V. Steinbrugge.
FIGURE 9.—Close-up view of the part of figure 8 indicated by the rectangle, showing the failure of the pier at the third floor level, cracking at each floor level at the corners of the building, and X-cracking.

INTRODUCTION

In the winter of 1811-1812 a series of three great earthquakes occurred in the New Madrid seismic zone. In addition to the three principal shocks, at least 13 other earthquakes, $M \geq VII$, occurred within a year of the first large earthquake on December 16, 1811. The three main shocks were felt over the entire eastern United States. They were strong enough to cause minor damage as far away as Indiana and Ohio on the north, the Carolinas on the east, and southern Mississippi on the south. They were strong enough to cause severe or structural damage in parts of Missouri, Illinois, Indiana, Kentucky, Tennessee, Mississippi, and Arkansas. The section of this poster titled "Seismic history of the New Madrid region" describes what happened in the epicentral region. Fortunately, few people lived in the severely shaken areas in 1811; that is not the case today. What would happen if a series of earthquakes as large and numerous as the "New Madrid" earthquakes were to occur in the New Madrid seismic zone today?

Photographs 1-10 show typical damage to structures that occurred during various earthquakes in the United States. Structural damage to buildings in the Modified Mercalli intensity scale as scale used for assigning numbers to earthquake effects, begins at intensity VIII. Minor or architectural damage (cracked plaster, windows, and chimneys) occurs at intensities VI and VII, and effects on people and small objects predominate at intensities below VI (earthquake felt, direction and duration noted, dishes broken). Photographs 1-10 illustrate damage caused by intensities VIII and above. None of the damage shown in these photographs occurred in earthquakes larger than the 1811-1812 New Madrid shocks, and most of the examples are from considerably smaller shocks. Photographs 1-4 and 7 show damage to masonry buildings, mostly old and unreinforced, none designed to be earthquake resistant. How many such buildings are in use in your community? Photographs 5 and 6 show damage to modern structures close to the epicenter of a magnitude 6.5 earthquake, a small shock compared to the magnitudes (8.4-8.7) of the New Madrid earthquakes. Photographs 8-10 are typical of damage that can occur at large distances from great earthquakes. Tall buildings are particularly susceptible to ground motions with relatively long periods (greater than 1 second), while short, rigid buildings are generally more likely to be damaged by ground motions with periods of less than 1 second. The period ground motions attenuate more rapidly with distance from the epicenter than do the longer period motions.

The 1811-1812 earthquakes produced extensive ground effects. Earthquakes can cause many different kinds of ground effects, ranging from minor fissures, slumps, and rockslides to major landslides and disturbances of the ground surface. Photographs 11-17 show typical earthquake ground effects and the kinds of damage they can cause to manmade structures.

In another earthquake as large as the 1811-1812 shocks really likely to occur in New Madrid seismic zone? Great earthquakes such as the 1811-1812 series are estimated to occur on the average every 500 years. However, earthquakes strong enough to cause structural damage (VIII in the Modified Mercalli intensity scale) are estimated to occur in the seismic zone on the average every 50 years. The last such shock occurred in 1843.

How do you prepare for a possible earthquake and what do you do if one occurs? The section on "Earthquake safety tips" explains what to do before, during, and after an earthquake.

Want to know more? See "Sources of additional information." Other reports of interest are listed in "References cited."

THE "SIZE" OF AN EARTHQUAKE

Magnitude

Magnitude is an instrumental measure of the "size" of an earthquake—that is the total amount of energy released by the earthquake. Several different magnitude calculations can be made from the amplitudes of the seismic vibrations recorded by a seismograph. The two most common ones are m_b derived from the body-wave vibrations which travel through the earth, and M_s derived from the surface-wave vibrations, which travel along the earth's outer crustal layers. Calculation of the magnitude of an earthquake takes into consideration the amplitude and period of the recorded vibrations and the distance of the seismograph from the source of the earthquake within the earth—the hypocenter. Thus, the same magnitude will be calculated from the recordings made by seismographs at different distances from the hypocenter. Because the first instrumental magnitude scale was developed in 1935 by Charles F. Richter, magnitude is commonly referred to as "the Richter scale."

Intensity

Intensity is a measure of the effects of an earthquake on people, animals, structures, and the ground. Intensity values are denoted by Roman numerals on the Modified Mercalli Intensity Scale (Wood and Neumann, 1931), which ranks seismic effects into twelve levels of increasing severity. An intensity map or isoseismal map for an earthquake is made by plotting on a map the intensities assigned to the effects produced by the earthquake at various places and then contouring the plotted values. The isoseismal or contour for the maximum intensity (I_0) usually includes the instrumentally located epicenter, the point on the earth's surface directly above the hypocenter.

For preinstrumental earthquakes, such as those that occurred in the New Madrid seismic zone in 1811-1812, no magnitudes or instrumentally-located epicenters are known, but intensities can be assigned on the basis of descriptive reports such as newspaper accounts. Intensities and isoseismal maps are used to estimate both the epicentral area and the magnitude of preinstrumental earthquakes. The epicenter is assumed to be near the center of the highest isoseismal, and the magnitude is usually estimated either from I_0 or from the size of the areas enclosed by the isoseismals.

EARTHQUAKE SURVIVAL TIPS

(Quoted and extracted in part from Gates, 1982)

The actual movement of the ground in an earthquake is seldom the direct cause of death or injury. Most casualties result from falling objects and debris. Earthquake-related injuries are commonly caused by (1) partial building collapse, such as toppling chimneys, falling brick from wall facings and roof parapets, collapsing walls, falling ceiling plaster, light fixtures, and pictures; (2) flying glass from broken windows (this danger may be greater from windows in high-rise structures); (3) overturned bookcases, fixtures, and other furniture and appliances; (4) fires from broken chimneys, broken gaslines, and similar causes (this danger may be aggravated by a lack of water with which to fight fire caused by broken mains); (5) fallen powerlines; and (6) direct human actions resulting from panic.

What You Can Do Before an Earthquake Occurs

1. Support the adoption and enforcement of building codes that have suitable requirements for earthquake-resistant design.
2. Check your home for earthquake hazards. Bolt down or provide other strong support for gas appliances and gaslines. Use flexible connections wherever possible.
3. Teach responsible members of your family how to turn off electricity and gas, and water at main switches and valves.
4. Provide for your family to receive instruction in basic first aid because medical facilities may be overloaded immediately after a severe earthquake.
5. Think about what you should do if an earthquake strikes when you are at home: at school driving your car; at work in a store, public hall, theater, or stadium.

What You Can Do During an Earthquake

1. If indoors, watch for falling plaster, bricks, light fixtures, high bookcases, and other furniture which might slide or topple. Stay away from windows, mirrors, and chimneys. If in danger, get under a table, desk, or bed in a corner away from windows or in a strong doorway. Usually, it is best not to run outside.
2. If in a high-rise office building, get under a desk. Do not dash for exits, since stairways may be broken and jammed with people. Never use elevators may fail.
3. If outside, avoid high buildings, walls, and power poles. Move to an open area away from all hazards.

What You Can Do After an Earthquake

1. Apply first aid or seek medical help for injured people.
2. Check for fires or fire hazards. Do not use matches, lighters, or open-flame appliances until you are sure that there are no gas leaks. Do not operate electrical switches or appliances if gas leaks are suspected.
3. Avoid downed powerlines or objects touched by the downed wires.
4. Obtain emergency water from water heaters, toilet tanks, melted ice cubes, and canned vegetables, if the water is safe.
5. Check to see that sewage lines are intact before permitting continued flushing of toilets.
6. Do not use your telephone except for genuine emergency calls.
7. Check your chimney. Unnoticed damage could lead to a fire. The initial check should be made from a distance. Approach chimneys with caution.
8. Do not go sightseeing. Keep the streets clear for passage of emergency vehicles.
9. Be prepared for additional earthquake shocks called "aftershocks."

SEISMIC HISTORY OF THE NEW MADRID REGION

Earthquakes of 1811-1812

During the winter of 1811-1812, three great earthquakes occurred in the Mississippi Valley, each having magnitude M_s 8.4 or higher. (See section on "The 'size' of an earthquake" for an explanation of magnitude and other related terms.) No earthquakes larger than these have occurred within the continuous United States during historic time. Their magnitudes are comparable to, and are probably larger than, those of the largest California earthquakes, and, because of the low attenuation of seismic intensities in the eastern and central United States, they were felt over areas much larger than the areas over which California shocks of similar magnitude are felt. The 1811-1812 earthquakes were felt with intensities greater than or equal to V on the Modified Mercalli intensity scale (that is, enough to cause alarm and knock small objects off shelves) over the entire eastern United States (Nuttli, 1973).

Main shocks of the 1811-1812 "New Madrid" earthquake sequence

(Nuttli, 1981)

Date	I_0	M_s	m_b
Dec. 16, 1811	XI	8.6	7.2
Jan. 23, 1812	X-XI	8.4	7.1
Feb. 7, 1812	XI-XII	8.7	7.3

Main shocks and aftershocks of the 1811-1812 "New Madrid" earthquake sequence

(Nuttli, 1981)

Number of shocks	I_0	M_s
3	X-XII	28
5	IX-X	7-8
10	VIII-IX	6-7

ACKNOWLEDGMENTS

The authors wish to thank Karl V. Steinbrugge for all his help and encouragement, both for providing earthquake damage photographs from his collection and for his comments and suggestions. Also, the assistance of Patricia A. Lockridge, of the NOAA National Geophysical Data Center, and of the staff of the U.S. Geological Survey Photographic Library was greatly appreciated.

SOURCES OF ADDITIONAL INFORMATION

Earthquakes in the Central United States

Dockel, Jerry, 1970, Earthquakes of the stable interior, with emphasis on the midcontinent: Lincoln, Neb., University of Nebraska, Ph.D. dissertation, v. 1, 169 p.; v. 2, 332 p.
Hopper, M. G., Algermissen, S. T., and Dobrovolsky, E. E., 1983, Estimation of earthquake effects associated with a great earthquake in the New Madrid seismic zone: U.S. Geological Survey Open-File Report 83-179, 101 p. [Prepared for Federal Emergency Management Agency (FEMA) Central United States Earthquake Preparedness Project (CUSEPP) Number 82-3].
Liu, Ben-chieh, Hsieh, Chang-tesh, Gustafson, Robert, Nuttli, Otto, and Gentile, Richard, 1981, Earthquake risk and damage functions—Application to New Madrid: Boulder, Colo., Westview Press, 237 p.
M & H Engineering and Memphis State University, 1974, Regional earthquake risk study: Mississippi-Arkansas-Tennessee Council of Governments/Memphis Delta Development District (MATCOG/MDD), Report no. MATCOG-DD-MHMSU-74-1013-11, 4 p. 57-93.

Nuttli, O. W., 1979, Seismicity of the central United States: Geological Society of America Reviews in Engineering Geology, 4, p. 57-93.
Penick, James, Jr., 1976, The New Madrid earthquakes of 1811-1812: Columbia, Mo., University of Missouri Press, 181 p.
Street, R., 1982, A contribution to the documentation of the 1811-1812 Mississippi Valley earthquake sequence: Earthquake Notes, v. 53, p. 39-53.

General earthquake information

Bolt, B. A., 1978, Earthquakes—A Primer: San Francisco, W. H. Freeman & Company, 241 p.
Coffman, J. L., von Hake, C. A., and Stover, C. W., 1982, Earthquake history of the United States: review with supplement: U.S. National Oceanic and Atmospheric Administration and U.S. Geological Survey Publication 41-1, 235 p.
U.S. Geological Survey, Earthquake Information Bulletin (Bimonthly): Washington, D.C., U.S. Government Printing Office. [For a complimentary copy write to Earthquake Information Bulletin, U.S. Geological Survey, MS 904, National Center, Reston, Va. 22092].
Hays, W. W., Algermissen, S. T., Eppinsos, A. F., Perkins, D. M., and Hinchey, W. A., 1973, Guidelines for developing design earthquake response spectra: Champaign, Ill., Construction Engineering Research Laboratory Technical Report M-14, 347 p.
Steinbrugge, K. V., 1982, Earthquakes, volcanoes, and tsunamis—an anatomy of hazards: New York, Stanzas America Group, 194 p.
United States Geological Survey, Annual publication. Published from 1928 to 1968 by the U.S. Department of Commerce, Coast and Geodetic Survey; for 1969 by the National Oceanic and Atmospheric Administration (NOAA), National Ocean Survey; from 1970 to 1972 by the NOAA Environmental Data Service; from 1973 to 1977 by the NOAA Environmental Data Service and by the U.S. Geological Survey; from 1978 to 1980 by the U.S. Geological Survey and the NOAA Environmental Data and Information Services; and for 1981 by the U.S. Geological Survey.
United States Geological Survey, Public Information Office, 1028 General Services Building, 19th and F Streets NW, Washington, D.C. 20546.

REFERENCES CITED

Algermissen, S. T., 1972, The seismic risk map of the United States, development, use, and plans for future refinement, in: Algermissen, S. T., ed., Conference on Seismic Risk Assessment for Building Standards, Washington, D.C., March 16, 1972, p. 11-16.
Bollinger, G. A., 1977, Reinterpretation of the intensity data for the 1886 Charleston, South Carolina, earthquake, in Rankin, D. W., ed., Studies related to the Charleston, South Carolina earthquake of 1886—A preliminary report: U.S. Geological Survey Professional Paper 102A, p. 17-31.
Fuller, M. L., 1912, The New Madrid earthquake: U.S. Geological Survey Bulletin 494, 119 p.
Gates, G. O., 1982, Safety and survival in an earthquake: Washington, D.C., U.S. Government Printing Office, 1982-361-618-155/28.
Johnston, R. O., 1973, Veterans Administration Hospital, in Murphy, L. M., ed., San Fernando, California, earthquake of February 9, 1971: U.S. National Oceanic and Atmospheric Administration, v. 1 of 3, pt. B, p. 655-665.
Johnston, R. O., and Strand, D. R., 1973, Olive View Hospital, in Murphy, L. M., ed., San Fernando, California, earthquake of February 9, 1971: U.S. National Oceanic and Atmospheric Administration, v. 1 of 3, pt. A, p. 229-232.
Kawasumi, Hiroshi, ed., 1968, General report on the Niigata earthquake of 1964: Tokyo, Japan, Tokyo Electrical Engineering College Press, 550 p.
Nuttli, O. W., 1973, The Mississippi Valley earthquakes of 1811 and 1812—Intensities, ground motion, and magnitudes: Seismological Society of America Bulletin, v. 63, p. 227-248.
———, 1981, Evaluation of past studies and identification of needed studies of the effects of major earthquakes occurring in the New Madrid fault zone: Kansas City, Mo., Federal Emergency Management Agency Region VII, Central United States Earthquake Preparedness Project (CUSEPP) Number 81-1, 28 p.
Olson, R. A., 1971, Individual and organizational dimensions of the San Fernando earthquake, in Murphy, L. M., ed., San Fernando, California, earthquake of February 9, 1971: U.S. National Oceanic and Atmospheric Administration, v. 2 of 3, p. 229-232.
Richter, C. F., 1958, Elementary seismology: San Francisco, W. H. Freeman & Company, 748 p.
Steinbrugge, K. V., Manning, J. H., and Degenskolb, H. J., 1967, Building damage in Anchorage, in Wood, F. J., ed., The Prince William Sound, Alaska, earthquake of 1964 and aftershocks: U.S. Coast and Geodetic Survey Publication 10-3, p. 7-217.
Wood, G. O., and Neumann, Frank, 1931, Modified Mercalli intensity scale of 1931: Seismological Society of America Bulletin, v. 21, p. 277-283.
Youd, T. L., and Olsen, H. W., 1971, Damage to constructed works, associated with soil movements and foundation failures, in The San Fernando, California, earthquake of February 9, 1971: U.S. Geological Survey Professional Paper 733, p. 126-132.

TYPES OF DAMAGE THAT COULD RESULT FROM A GREAT EARTHQUAKE IN THE NEW MADRID, MISSOURI, SEISMIC ZONE

By

Margaret G. Hopper and S. T. Algermissen

1984