

Map 1. Surface fractures and other earthquake-induced features formed in Potrero Canyon in association with the 1994 Northridge earthquake (see Fig. 1). Features mapped by P.J. Rymer, T.J. Powers, F.R. Chel, T.E. Fumal, D.P. Schwartz, J.C. Hamilton, and J.A. Treiman, 1994. Manuscript approved for publication February 20, 2001.




Figure 1. San Fernando Valley, California, area, showing the location of the Potrero Canyon, Tapo Canyon, and McBean Parkway study areas relative to the 17 January 1994 Northridge earthquake epicenter (solid star). Dashed line, boundary of strong ground motion greater than 0.5 g.




Figure 2. Surface fractures on north side of Potrero Canyon showing better developed cracks on west side of ridge spot that protrudes into canyon. Aerial photograph of surface fractures, prominent fractures marked by arrows. Features seen on cultivated ground include flower marks, tractor turn marks (see crop circles), and cattle trails. Late drawing of same area shown in 4. Heavy red lines, surface fractures.





Figure 3. Surface fracture with large vertical component of slip on north side of Potrero Canyon. Fracture developed at base of hill slope, near contact between alluvium and alluvium. View to the northeast.




Figure 4. Extensional surface fractures on south side of side canyon located south of Potrero Canyon. Fracture set occurs as narrow zone in east-south-east pattern. View to the northeast.




Figure 5. Map of horizontal slip direction across matching soil block irregularities plotted relative to surface fractures in Potrero Canyon. Two hollow arrows in the northeast indicate horizontal displacement directions of main strike fractures on the ground surface; these are marked with S = tank of soil ash and T = transformer.




Figure 6. Slant view of trench exposure DC-4 south of Holmes Place (down from a 35-mm scale). North wall of trench is shown. Trench depth is approximately 3 m below street level. Bedrock, represented by east-dipping bedding features, is Potrero (?) Formation. Multiple low-angle thrust faults (thick black lines) document a history of previous displacements that have folded the coarse sediments of the Potrero (?) Formation. 1994 rupture zone with vertical uplift on the surface (left of this view). Surface warping in 1994 mirrored in the older folding and was probably accompanied by incremental growth of the structure.



Figure 7. Broad zone of surface fractures, located between vertical and diagonal arrows, on north side of Potrero Canyon. Fractures below vertical white arrows in midground show stair-step pattern indicative of valley fill, located to right, that moved away from bedrock. View to the northeast.




Figure 8. Photograph of trench exposure DC-4, south of Holmes Place (see Map 2 for location and Fig. 7 for logs).



Figure 9. Photograph of trench exposure DC-4, south of Holmes Place (see Map 2 for location and Fig. 7 for logs).



Figure 10. Photograph of trench exposure DC-4, south of Holmes Place (see Map 2 for location and Fig. 7 for logs).

**INTRODUCTION**

The magnitude 6.7 (M<sub>w</sub> 7.0) Northridge earthquake of 17 January 1994 strongly shook the Los Angeles area region, resulting in 31 direct deaths, more than 20,000 people forced out of their homes, and an estimated \$20 billion in damage (Hall, 1994). The earthquake was caused by slip on a previously unrecognized south-dipping fault beneath the San Fernando Valley. Slip on the fault propagated from a depth of about 15 km below the ground surface (USGS and SCEC, 1994). Although there was no surface faulting associated with the causative fault, surface fractures did develop along the San Gabriel Mountains, Santa Susana Mountains, and other recognized faults (Hart and others, 1995; Hekker and others, 1995a, 1995b; Rymer and others, 1995; Treiman, 1995). The term "surface fractures" is used herein to describe ground breaks that are associated with primary faulting or with triggered secondary surface faulting on a steep seismogenic fault.

This report describes fault- and nonfault-related surface fractures that occurred at three sites, Potrero Canyon, Tapo Canyon, and the McBean Parkway area, 22 to 28 km north-northwest of the main shock (Fig. 1). Investigation of these sites documents far-reaching effects of even moderately large earthquakes. Study of such effects has become increasingly important, with further urbanization and development. Hekker and others (1995a, 1995b) documented the distribution of surface deformation associated with the Northridge earthquake in the Santa Susana Mountains.

The search for surface faulting and surface fracturing was initiated within hours of the earthquake. Both ground and airborne photographs, as well as aerial photographs, revealed surface fractures were found in Potrero Canyon, aerial photographs were taken of the area (including the McBean Parkway site) by K. Curtis, on 21 January 1994, at scales of about 1:2,000 and 1:6,000. These aerial photographs were studied under high magnification to supplement ground-based observations of surface fractures.

**FRACTURES IN POTRERO CANYON**

Potrero Canyon, a 5-km-long, 200-m-wide, east-west trending valley incised into the Pliocene Pico Formation (Whitener and Darton, 1962), is situated on the slip projection of the seismogenic rupture plane of the main shock. Local secondary or side canyons, notably two such features on the south side, extend from Potrero Canyon. Valley fill within Potrero Canyon consists of Holocene and late Pleistocene alluvium (silt, sand, and conglomerate) with a thickness of at least 15 to 20 m (Hekker and others, 1995; Cashings and others, 1996).

Extensive sets of surface fractures formed in alluvium around the margins of Potrero Canyon in association with the earthquake. Map 1 is a plot of the fractures, which extend east-west and north-south about 1.6 km and 1.1 km, respectively. Most fractures are in the upper 50 cm of the bedrock and alluvium contact at depth, near the base of the hill slopes (Figs. 2, 3). In areas where bedrock can be traced to the hill slopes, surface cracks were associated with this bedrock-alluvium contact in spite of the artificial change in topography.

Characteristics of surface fractures varied somewhat along the north and south sides of the canyon. On the north side of Potrero Canyon, discontinuous crack sets developed with extensional displacements, commonly in areas as wide as 30 m (Map 1). Fractures found along the south side were most commonly restricted to discontinuous narrow zones (Fig. 4), and there were smaller fractures moved toward the north side of the canyon, including the south edge of a side canyon that extends to the southeast from Potrero Canyon (Map 1).

Characteristically, surface fractures on both sides of Potrero Canyon and the side canyons were more common or more pronounced on the west sides of open ridge protrusions into the canyon (Map 1, Fig. 5). Fractures on the north side of the canyon have left-stepping crack sets and those on the south side have right-stepping sets, indicating a reverse-sense displacement. Measurements of horizontal slip directions across individual fractures and some of the narrower crack sets similarly indicate a general westward motion of the alluvial fill (see horizontal slip arrows in Fig. 6). In addition, fractures on both sides of the canyon dip steeply toward the center of the canyon.

Slip along fractures in Potrero Canyon was dominantly extensional, with small amounts of horizontal slip. Slip components were recorded only across single cracks and, because of the generally shallow dip of the fractures (Map 1, Figs. 2, 3), these measurements did not measure strike-slip. Also, rigid manmade features that best record displacement are not present in Potrero Canyon. Thus, our measurements do not record the total slip associated with this earthquake. Because of the scarcity of data, we cite only the horizontal displacement (Fig. 6). The closest approximation of total slip at a site is a measurement on the north side of the canyon about 400 m east of the western end of fractures. At this site, measurements across three of the larger cracks in a broad zone of fractures totaled more than 50 cm. Crack field estimates of maximum values of slip for the vertical, compressional, and extensional components of slip are about 1 m, 0.2 m, and 0.2 m, respectively.

Compressional fractures found along the south side of the canyon are believed to be shallow surficial features developed in or slightly below the soil layer. Trench exposures described in detail in Rymer and others, 1995 revealed compressional fractures that were antithetic to the larger, mostly extending extensional fractures. Compressional cracks exposed in the trenches represented slip only in the upper 50 cm of sediment, whereas extensional fractures were traced to depths of greater than 1 m without indication of slip-plane shallowing.

**LANDSLIDES AND OTHER GROUND FAILURES**

The 17 January earthquake triggered thousands of landslides throughout the greater Los Angeles region (Hobson and others, 1994; Hery and Hobson, 1995), including numerous slides that formed in the Potrero Canyon area. Although Hery and Hobson (1995) show some landslides in the Potrero Canyon area, their mapping of landslides was from small-scale aerial photographs that show only larger slides. We mapped dozens of small landslides, which were mainly exposed in the field on the 1:2,000-scale aerial photographs, in the hills surrounding Potrero Canyon (landslides are not shown in Map 1). The most common landslide types in the Potrero Canyon area were, in decreasing order of abundance, soil falls, soil slides, rock falls, and soil slumps. The volume of individual earthquake-induced landslides in the Potrero Canyon area varied, but most commonly was less than 10 cubic meters. Landslides were most common in road cuts and along the edges of artificial fill. Landslides on the north side of the canyon were quite extensive; local slides ranged from the ridge crest near the individual alluvial units along the canyon margin.

Cracks along ridge crests, slumped ridge effects not associated with landslides, also formed in Potrero Canyon area in association with the Northridge earthquake. We saw these features on ridge crests in Potrero Canyon, but because a systematic survey was not made of their distribution, a summary is not given.

Sandbars formed at several places in the valley floor of Potrero Canyon (Map 1). They were most prevalent near the south edge of the canyon, away from the principle stream channel and subsidiary drainages. The sandbars formed in the upper 1 to 2 m of sediment, which locally coalesced into zones tens of meters long. A discussion of sandbars and their source beds is presented by Hekker and others (1995).

**PIPE BREAKS**

Other earthquake-induced features in Potrero Canyon include pipe breaks in an east-west-trending natural gas line. Ten pipe breaks in small failures at pipe welds (D. Oberker, Caltech University, personal communication, 1994). The breaks were not located with surface fractures (Map 1); pipe breaks were probably due to strong shaking, liquefaction, or differential downward motion of alluvial fill rather than to movement along surface fractures.

**GEOTECHNICAL AND GEOPHYSICAL MEASUREMENTS**

**ACROSS SURFACE FRACTURES**

A quadrilateral and other geologic measurements were installed across breaks in Potrero Canyon to measure possible afterglow. The quadrilateral is located across surface cracks that contained both extensional and compressional cracks (Map 1). Reported distance measurements of the quadrilateral were made on the quadrilateral. Measurements were made 7, 11, 16, and 57 days after the earthquake with a Wild T2020/DEM0 total station. Analysis of horizontal distances between quadrilateral measurements and the other geologic measurements shows only random motion, with uncertainty levels commonly in the 1 to 2 mm range, and occasionally up to 4 mm.

Two additional measurements were installed in bedrock highs on the north and south flanks of Potrero Canyon to measure possible net slip across the whole canyon. The line between these two measurements was measured 7, 11, and 16 days after the earthquake. Line lengths varied between the first and second surveys by 0.9 mm, and between the second and third surveys by 0.5 mm, measurements which are within the set-up error. There was no indication of postseismic movement (postseismic movement uncertainty).

A high-resolution seismic reflection and refraction survey was run across Potrero Canyon in February 1994 to better understand the subsurface structure and its possible relation to fractures seen on the ground surface (Cashings and others, 1996). The location of the seismic profile near the west end of the canyon is shown in Map 1. Cashings and others (1996) found apparent south-dipping reverse faults beneath Potrero Canyon. Given the nature of surface fractures mapped in Potrero Canyon (Map 1) with net right-oblique slip on the north side of the canyon and left-oblique slip on fractures on the south side, we find it unlikely that the surface fractures represent coseismic slip on deep-seated faults. However, the apparent faults imaged in the seismic survey may have added further focused shaking to the Potrero Canyon area.

**DISCUSSION**

Our surface investigations, along with trenching studies reported in Rymer and others (1995), indicate that primary faulting did not occur in Potrero Canyon. Rather, we conclude that the surface fractures likely formed in response to strong shaking that resulted in alluvial compaction. Stratigraphic and structural relations exposed in trenches on the south margin of the valley are consistent with surface displacements resulting from differential settlement and faulting (recorded as shallow thrusts) due to strong ground motion. Movement took place largely along the bedrock-alluvium contact but possibly also involved the soft sediment part of the bedrock. The distribution and types of earthquake-induced features found in Potrero Canyon are also generally consistent with deformation due to strong ground motion rather than to surface faulting. The net down-canyon motion of the alluvial canyon fill (Fig. 6) supports this model, as does the presence of localized liquefaction, pipe breaks, and better developed cracks on the western (down-gradient) sides of ridge spots (Map 1, Fig. 5).

Unusually high strong ground motions recorded 10 to 25 km north of the epicenter are suggestive of slip displacement during rupture of the earthquake (Wald and others, 1996). A station at the east end of Potrero Canyon recorded a peak ground velocity of about 115 cm/sec; the width of the velocity pulse is about 2 sec. Such fracture energy 2 sec after the rupture projection on the causative fault may have contributed to the observed ground deformation in Potrero Canyon. Southeast-directed horizontal movement of a 70-percent full, 3.789-liter tank of water, which moved 35 cm, and a transformer, which moved 5 cm, (Fig. 6) are further indicators of the north-northeast directed strong ground motions sustained in Potrero Canyon.

**BEDDING-PLANE FAULTING IN THE McBEAN PARKWAY AREA**

Ground rupture more closely related to tectonic deformation occurred a few kilometers east of Potrero Canyon (Treiman, 1995; Fig. 1), where bedding-plane slip was found in the soil on the north flank of the Santa Susana Mountains, along the up-slope projection of the rupture plane. The most continuous zone of surface rupture was about 20 m long, with additional discrete fractures for another 150 m to the north (Map 2).

The artificial profile of the area of faulting is simple (Treiman, 1986; Whitener and Darton, 1962). Sandstone and siltstone beds of the Pleistocene near-marine Sangas Formation are inclined to the northeast at 40° to 60°. This section of tilted strata lies roughly midway between the axis of the Pico Formation to the south and the broader Santa Clara syncline to the north. The Sangas Formation is unconformably overlain by the flat-lying to moderately north-south-dipping sands and gravels of the late Pleistocene Potrero (?) Formation, a local fluvial and colluvial basin fill deposit laid down within the past 76,000 years. Local angular unconformities have developed within the Potrero (?) Formation in response to continued late Quaternary deformation.

During the Northridge earthquake, reverse slip occurred along at least five bedding planes within the Sangas Formation that had been exposed in recently graded bedding pools and cut slopes of a residential development west of Figure 5 (Map 2). No buildings had been constructed on the affected beds. Fault displacement was consistently northeast-southwest, with measured slips of up to 19 cm; lateral separations varied from 4 cm right-lateral to 0.7 cm left-lateral, with left-lateral slip predominating. Individual ruptures were clearly compressioned in nature and were expressed by low southwest-facing scarps. The most continuous rupture extended for about 250 m and had a general trend of N40°W. An exposed in a bedrock cut slope at its southeastern extremity, the fault surface dips 37°NE. Exposures in exploratory trenches confirmed that the faulting occurred along bedding planes, usually within a clayey silt (Gibbs, 1995; Seaward, 1995b). Small, parallel rupture lay approximately 40 to 80 m to the northeast. One of these was traced part way up a cut slope at the northern margin of the development.

The ruptures to the northeast were associated with ground surface warping. At Holmes Place, the road cut were monotonically warped down to the northeast about 15 cm across a zone about 6 m wide, even though individual surface breaks showed the reverse sense of displacement, southeast side down. Compression was also indicated by shortening of the sidewalk and curb. The surface faulting and warping are associated with strongly deformed Potrero (?) Formation. Three other faults showed from 50° to horizontal within a distance of 10 m. These other faults have been folded and faulted across a relatively narrow zone, generally less than 8 m. Bedding within the Potrero (?) Formation is locally overturned (Fig. 7). In addition to the northeast-dipping bedding-parallel faults, the rocks have been displaced in the past by multiple southwest-dipping great faults. Warping across Fitzgerald Avenue, south of Holmes Place, was similar in magnitude but was broader, at least 20 m vertical movement across a 25 m wide zone. A post-earthquake leveling survey (Gibbs, 1995) shows that the block defined by the width of the zone of deformation had been uplifted nearly 1 foot (30 cm), with relatively little internal deformation and cracking in this area.

To the southeast of the residential development, a normally to northeast-oriented closed depression, about 70 m long and 40 m wide, is aligned with the zone of faulting (Map 2). Several trenches across this depression revealed only a few discontinuous fractures in the soil with an measurable displacement. A large bedrock and bedrock excavation (F.5) by Seaward (1994) revealed gently to moderately northeast-dipping strata of the Potrero (?) Formation with numerous fractures and scars. These included both northeast- and southwest-dipping reverse faults, similar to the bedding-parallel faults, and southwest-dipping thrust faults, similar to the trench exposure near Holmes Place (DC-4). None of the bedrock trenches could be shown to have moved in the recent earthquake.

**SURFACE FRACTURES FORMED IN THE POTRERO CANYON, TAPO CANYON, AND McBEAN PARKWAY AREAS IN ASSOCIATION WITH THE 1994 NORTHRIDGE, CALIFORNIA, EARTHQUAKE**

By  
MICHAEL J. RYMER<sup>1</sup>, JEROME A. TREIMAN<sup>2</sup>, THOMAS J. POWERS<sup>1</sup>, THOMAS E. FUMAL<sup>1</sup>,  
DAVID P. SCHWARTZ<sup>1</sup>, JOHN C. HAMILTON<sup>1</sup>, and FRANCESCA R. CINTI<sup>3</sup>

<sup>1</sup> U.S. Geological Survey, Menlo Park, CA 94025  
<sup>2</sup> California Department of Conservation, Division of Mines and Geology, Los Angeles, CA 90012  
<sup>3</sup> Istituto Nazionale di Geofisica, Roma, Italia