













EXPLANATION

-  Morainal deposits
-  Talus
-  Pegmatite
(Differentiated from granite in drill holes only)
-  Predominantly granite
-  Predominantly metasedimentary rocks
-  Contact
-  Fault of surface
-  Fault in drill hole
-  Shear zone of surface
-  Shear zone in drill hole
-  Drill holes projected into line of section
-  Fracture density along tunnel line
 $<0.1-0.5$ $0.5-1$ $1-3$
-  Average distance between fractures, in feet



Profile from Continental Engineers Inc., project 1-70-3(13)212
Furnished by Colorado Department of Highways

Compiled by C.S. Robinson and F.T. Lee, 1962





Figure 5A

PREDICTED GEOLOGIC SECTION AND ENGINEERING DATA ALONG THE PROPOSED STRAIGHT CREEK TUNNEL LINE

Stations 31+00 to 60+00



This report and/or map is preliminary and has not been edited or reviewed for conformity with Geological Survey standards or nomenclature.