

# **GWPD 16—Measuring water levels in wells and piezometers by use of a submersible pressure transducer**

**VERSION:** 2010.1

**PURPOSE:** To make continuous water-level measurements in a well or piezometer by using a submersible pressure transducer.

## **Materials and Instruments**

1. Vented submersible pressure transducer, data logger or data collection platform (DCP), cables, suspension system for the transducer and cables (wire ties or other semipermanent devices), and power supply
2. Data-readout device (i.e., computer loaded with correct software) and data storage modules or other media
3. Locked well cover or recorder shelter and key
4. A water-level tape (steel or electric) graduated in feet, tenths and hundredths of feet, and other materials necessary for depth-to-water measurement
5. Forms including:
  - a. Well completion form
  - b. Logbook with records of previous measurements for comparison
  - c. Transducer calibration worksheet
  - d. Water-level measurement field form or groundwater inspection sheet
6. Pencil or pen, blue or black ink. Strikethrough, date, and initial errors; no erasures
7. Calculator
8. Watch
9. Field notebook
10. Spare dessicant
11. Replacement batteries
12. Cleaning supplies for water-level tapes as described in the National Field Manual (Wilde, 2004)
13. Tools including:
  - a. High-impedance (digital) multimeter
  - b. Connectors
  - c. Crimping tool
  - d. Contact-burnishing tool or artist's eraser

## **Data Accuracy and Limitations**

1. Water-level measurements for the in-place calibration of pressure transducers should be made to the nearest 0.01 foot.
2. The accuracy of a pressure transducer differs with the manufacturer, measurement range, and depth to water. The measurement error and accuracy standard for most situations are 0.01 foot, 0.1 percent of range in water-level fluctuation, or 0.01 percent of depth to water above or below a measuring point (MP), whichever is least restrictive.
3. Pressure transducers are subject to drift, offset and slippage of the suspension system. For this reason, the transducer readings should be checked against the water level in the well on every visit, and the transducer should be recalibrated periodically and at the completion of monitoring.

## Advantages

1. Water levels can be collected at user-defined time scales without making individual manual measurements.
2. Small size allows water levels to be measured in wells or piezometers that are of small diameter, crooked, angled, or that contain pumps or other equipment.
3. The data logger can be left unattended for prolonged periods until data can be downloaded to a portable computer in the field.
4. Some pressure transducers with integrated data loggers are small enough to be placed inside the protective well casing and do not require a separate shelter. Good for high visibility, secure, or below-ground installations.
5. Downloaded data can be imported directly into a spreadsheet or database.
6. Can be interfaced with a DCP to transmit data collected via satellite for near real-time data reporting.
7. Can be installed in a flowing well.

## Disadvantages

1. It may be necessary to correct the data for instrument drift, hysteresis, temperature effects, and offsets.
2. Transducers only operate in a limited water-level (pressure) range. The unit must be installed at the appropriate depth in a well so that the water level occurs within the measurement range of the pressure transducer. Wells with a large difference between maximum and minimum water levels may be monitored with reduced resolution using a pressure transducer with a higher range or may require frequent resetting of the depth of the transducer during site visits.
3. Materials in the transducer and cable may react with substances present in the water, causing damage or failure of the instrument.
4. Rapid water-level fluctuations may be missed if they occur between the programmed water-level measurement times.
5. With some data loggers, stored water-level measurements may be lost if the power supply fails.

## Assumptions

1. A permanent MP has been established as described in GWPD 3.
2. The user is familiar with the transducer specifications and limitations and has evaluated the required accuracy of the measurements in accordance with the objectives of the study. The transducer's range is appropriate for the range of water levels expected in the observation well (the operating range will not be exceeded).
3. The transducer has been calibrated, either by the manufacturer or by the user, for the conditions expected in the field installation.
4. The transducer is vented to the atmosphere. Data from an absolute transducer must be adjusted to account for changes in atmospheric pressure.
5. If the user is visiting an existing installation, the vent tube is unobstructed, the desiccant is in place, and the well is free of obstructions.


## Instructions

This procedure is limited to the installation of vented pressure transducers in observation wells and piezometers for long-term monitoring of water levels (fig. 1). For additional information, and for other applications, see Freeman and others (2004, p. 25–34).

1. If preparing a new installation:
  - a. Check that the well is unobstructed. Clear obstructions as described in GWPD 6.
  - b. If the well depth is not known, measure the total well depth as described in GWPD 11.
  - c. If necessary, install an instrument shelter that will protect the transducer and data logger from vandalism and weather.
  - d. Keep the transducer packaged in its original shipping container until it is installed. Connect the transducer, data logger, power supply, and ancillary equipment. Record the model, serial number, and pressure range of the transducer in the field notebook.
  - e. Install the pressure transducer by lowering it into the well so that it is submerged below the water surface. Avoid dropping the transducer or permitting sharp contacts with the sides of the well casing. Do not allow the transducer to free fall into the well.

- f. Conduct a field calibration of the transducer by raising and lowering it over the anticipated range of water-level fluctuations (Freeman and others, 2004, p. 29). Take three readings at a minimum of five intervals each, during both the raising and lowering of the transducer. Record the data on a calibration worksheet (fig. 2). Calculate a calibration equation for the transducer using the results in figure 2 and a regression equation. If a correction is necessary, apply the correction to the data logger or during post-processing of the water-level record.
- g. The transducer should be installed at a point in the well that will not go dry. Estimate the lowest expected water level, and lower the transducer to the desired depth below the water level.
- h. Fasten the cable or suspension system to the well head using tie wraps or a weatherproof strain-relief system. If the vent tube is incorporated in the cable, make sure not to pinch the cable too tightly or the vent tube may be obstructed.
- i. Make a permanent mark on the cable at the hanging point so that future slippage, if any, can be determined.

- j. Record the well and measuring point (MP) configuration, by drawing a sketch (GWPD 3). Include the MP correction length above the land surface, the hanging point, and the hanging depth (fig. 1).
  - k. Measure the static water level in the monitor well with a steel (GWPD 1) or electric tape (GWPD 4).
1. Configure the data logger to ensure the channel, scan intervals, and other functions selected are correct. Activate the data logger and set the correct time.
  2. If visiting an existing installation:
    - a. Retrieve groundwater data by using instrument or data logger software.
    - b. Inspect the equipment to confirm that installation is operating properly. Document the current water level recorded by the sensor (not the most recent water level recorded by the data logger).
    - c. Measure the depth to water in the well using either GWPD 1 or GWPD 4 to obtain an accurate water-level measurement to compare with the water level measured by the transducer.
    - d. Record the final water-level measurement on the Inspection of Continuous Record Well field form (fig. 3).
    - e. If the water-level measurement and transducer reading differ, raise the transducer in the well slightly and take a reading to confirm that the sensor is working. Observe for possible cable kinks or slippage. Return transducer exactly to its original position.
    - f. Recalibrate the transducer as described in part 1f if necessary (fig. 2).
    - g. If the water-level measurement differs from the instrumentation reading by an amount specified in the groundwater quality assurance procedures of the local office, record it on the inspection sheet and reset the instrumentation to reflect the proper depth to water.
    - h. Use the multimeter to check the charge on the battery, and the charging current supply to the battery. Check connections to the data logger, and tighten as necessary. Burnish contacts if corrosion is occurring. Check dessicant. Replace if necessary.
    - i. Verify the logger channel and scan intervals, document any changes to the data logger program, and reactivate the data logger. Make sure the data logger is operating prior to departure.



**Figure 1.** Submersible transducer in an observation well (Freeman and others, 2004, p. 27).

U.S. GEOLOGICAL SURVEY  
 CALIBRATION WORKSHEET FOR SUBMERSIBLE TRANSDUCERS

Data Processing No: \_\_\_\_\_  
 Page \_\_\_\_\_ of \_\_\_\_\_

Site Name: Official USGS site name Site ID and Number: 8 or 15 digit USGS Site ID

M.P. used: Nested piezometers often have multiple measuring points Party: \_\_\_\_\_

Date (mm/dd/yy):      /      /      Julian:      Watch Time:      EST CST MST PST Daylight UTC (circle)

Measuring Device: i.e. Calibrated steel tape, calibrated electric tape.

Transducer Information:  
 Date:      Type:      Length:      Serial No.      Output     

Units of reading: mv, psi, ma Range: i.e. 0-5 psi Conversion to feet: 2.3067 x psi = range of 0 to 11.534 ft.

Calibration marks: Describe what was used to mark the transducer cable for measuring distance moved during the calibration process.

Out-of water reading:      /      Set Point reading:      /      Scan Rate:      Reset? Yes No

Time	Measured Water Level	Cal. Mark	Dist. btwn. Marks	Total Dist.	Readings			
1014	22.35 DBLS	1	1.00	1.00	0.4334 psi			
1015					0.4337			
1016	22.35		1.50		0.4332			
1022	22.35	2		2.50	1.0838 psi			
1023					1.0841			
1024	22.35		1.50		1.0840			
1030	22.34	3		4.00	1.7341 psi			
1031					1.7337			
1032	22.34		1.50		1.7339			
1039	22.33	4		5.50	2.3843			
1040					2.3846			
1041	22.33		1.50		2.3844			
1047	22.33	5		7.00	3.0346			
1048					3.0342			
1049	22.33		1.00		3.0351			
1058	22.32	6		8.00	3.4682			
1059					3.4685			
1100	22.32		1.00		3.4678			
1106	22.32	5		7.00	3.0392			
1107					3.0388			
1108	22.32		1.50		3.0390			
1114	22.32	4		5.50	2.3887			
1115					2.3889			
1116	22.32		1.50		2.3891			
1120	22.31	3		4.00	1.7514			
1121					1.7516			
1122			1.50		1.7517			
1126	22.31	2		2.50	1.1011			
1127					1.1013			
1128	22.31		1.50		1.1010			
1134	22.31	1		1.00	0.4509		WT. rise of 0.04 ft. during calib.	
1135					0.4507			
1136	22.31 DBLS		1.00		0.4507			

Figure 2. Calibration worksheet for submersible transducers (Freeman and others, 2004, p. 30).



## Data Recording

All data times of measurement are recorded in the field notebook or trip log and on the Inspection of Continuous Record Well field form or water-level measurement field form. Depending on the type of data logger used, data from the data logger are transferred to the office computer via field computer or a data module.

## References

- Cunningham, W.L., and Schalk, C.W., comps., 2011a, Groundwater technical procedures of the U.S. Geological Survey, GWPD 3—Establishing a permanent measuring point and other reference marks: U.S. Geological Survey Techniques and Methods 1–A1, 13 p.
- Cunningham, W.L., and Schalk, C.W., comps., 2011b, Groundwater technical procedures of the U.S. Geological Survey, GWPD 4—Measuring water levels by use of an electric tape: U.S. Geological Survey Techniques and Methods 1–A1, 6 p.
- Cunningham, W.L., and Schalk, C.W., comps., 2011c, Groundwater technical procedures of the U.S. Geological Survey, GWPD 6—Recognizing and removing debris from a well: U.S. Geological Survey Techniques and Methods 1–A1, 4 p.
- Cunningham, W.L., and Schalk, C.W., comps., 2011d, Groundwater technical procedures of the U.S. Geological Survey, GWPD 11—Measuring well depth by use of a graduated steel tape: U.S. Geological Survey Techniques and Methods 1–A1, 10 p.
- Cunningham, W.L., and Schalk, C.W., comps., 2011e, Groundwater technical procedures of the U.S. Geological Survey, GWPD 14—Measuring continuous water levels by use of a float-activated recorder: U.S. Geological Survey Techniques and Methods 1–A1, 6 p.
- Freeman, L.A., Carpenter, M.C., Rosenberry, D.O., Rousseau, J.P., Unger, Randy, and McLean, J.S., 2004, Use of submersible pressure transducers in water-resources investigations: U.S. Geological Survey Techniques of Water-Resources Investigations, book 8, chap. A3, 50 p.
- Lapham, W.W., Wilde, F.D., and Koterba, M.T., 1995, Ground-water data-collection protocols and procedures for the National Water-Quality Assessment Program—Selection, installation, and documentation of wells, and collection of related data: U.S. Geological Survey Open-File Report 95–398, 69 p. + errata.
- Wilde, F.D., ed., 2004, Cleaning of equipment for water sampling (version 2.0): U.S. Geological Survey Techniques of Water-Resources Investigations, book 9, chap. A3, section 3.3.8, accessed May 17, 2010, at <http://pubs.water.usgs.gov/twri9A3/>.