

Prepared in cooperation with the Southwest Florida Water Management District

Hydrologic Conditions that Influence Streamflow Losses in a Karst Region of the Upper Peace River, Polk County, Florida



Scientific Investigations Report 2009-5140

U.S. Department of the Interior
U.S. Geological Survey

Cover: *Photos by P.A. Metz, USGS Monitoring of Gator Sink (right); Dover Sink (left) during Tropical Storm Alberto, June 12, 2006.*
Design by Jim Tomberlin

Title page: Drying riverbed upstream from Peace River near Bartow gage, May 2008.

Contents: Rockfall at the entrance to Dover Sink.

