



Photo 04JHBF14. Buff-colored Al- and Fe-rich precipitate along Foster Creek downstream of Lago Creek and all acidic inflows.