



5.—Oak tree damaged by impact from a displaced boulder (station 9)

California associated with earthquakes: U.S. Geological Survey Professional Paper 993, 177 p.

Youd, T. L., and Perkins, D. M., 1978, Mapping liquefaction-induced ground failure potential: Journal of the Geotechnical Division, American Society of Civil Engineering, v. 104, no. GT4, Proceeding Paper 13659, p. 433-446.

(fig. 3). According to this model, the first part of the slope to fail (at low seismic stress levels) lies near the midpoint of the slope, where a concentration of tensile stresses develops. This region fails once the tensile strength of the intact rock or of any discontinuities is exceeded. The geometry of the failures at stas. 35, 38, 39, 40, and 42 indicates that this model accurately predicts some of the observed failures in weakly cemented materials.

Youd, T. L., and Perkins, D. M., 1978, Mapping liquefaction-induced ground failure potential: *Journal of the Geotechnical Division, American Society of Civil Engineering*, v. 104, no. GT4, Proceeding Paper 13659, p. 433-446.