









MINE SHAFT ABANDONMENT PROCEDURES



792-1050 R36 11/79