



EXPLANATION

- 2 + 00  
Survey centerline of original workings, showing survey stations
- Outline of workings, after 50-ton shot; some conventions as for 10-ton shot
- Bedding plane of rocks, shown only as encountered in new workings
- New workings to explore effect of 50-ton shot
- 55W  
Fractures and faults produced by 50-ton shot, showing dips where necessary
- Walls of Raise II, with timbers; base of each wall moved outward as indicated by dashed lines
- Clay bags, shown only in part
- Rubble broken by 50-ton shot as exposed in Raise I and II and at Face I

EFFECT OF 50-TON SHOT ON GEOLOGY AND WORKINGS, USGS TUNNEL AREA, NEVADA TEST SITE

