Route 478^{+h} Ave Stream $8ig \le 100 \times River$ MRM Date $8/8/10$ Initials GPS coordinates: $8/120044$ Location $5.5 \times 1.5 \times 1.5 \times 1.29 \times 1.21$ GPS coordinates: $8/14^{\circ}0.7/56.0^{\circ}$ taken from: USL abutment $8/120044$ centerline of $1/120044$ MRM end Datum of coordinates: WGS84 $1/120044$ NAD27 Sq. mi. The average bottom of the main channel was $1/1600000000000000000000000000000000000$						
MISCELLANEOUS CONSIDERATIONS						
Flows	$Q_{100} = 23900$			$Q_{500} = 36000$		
Estimated flow passing through bridge	23900			33426		
Estimated road overflow & overtopping				2174		
Consideration	Yes	No	Possibly	Yes	No	Possibly
Chance of overtopping		X,		X		
Chance of Pressure flow		X			X	
Armored appearance to channel		X			X	
Lateral instability of channel		X			X	
Riprap at abutments? Yes No Marginal A lot was washed away Evidence of past Scour? Yes No Don't know Debris Potential? High Med Low Does scour countermeasure(s) appear to have been designed? Riprap Yes No Don't know NA Spur Dike Yes No Don't know NA Other Yes No Don't know NA Bed Material Classification Based on Median Particle Size (D ₅₀)						
Material Silt/Clay Sand		Gravel		Cobbles		Boulders
				64-250		>250
Comments, Diagrams & orientation of digital photos 1166 - Bridge # 71 - RBUS 67 - US Face of bridge 72 - LBUS 68 - Left Abut. US 69 - R. Abut. US 70 - US from bridge						
Summary of Results						
	Q100			Q500		
Bridge flow evaluated	23900			33826		
Flow depth at left abutment (yaLT), in feet	4.3 3.2			6.2.		
Flow depth at right abutment (yaRT), in feet	3.4			7.2		
Contraction scour depth (ycs), in feet	6.9 6.8 13.8			5-15/		
Pier scour depth (yps), in feet	120			6.8		
Left abutment scour depth (yas), in feet	11.9			126		
Right abutment scour depth (yas), in feet	Right abutment scour depth (yas), in feet 11,9 13.6 IFlow angle of attack					
mgiv vi minor						1