



USGS Water-Resources Investigations Report 00-4261
 Figure 14. Downstream profiles of aluminum (top) and iron (bottom) loads in Daisy Creek and the Stillwater River, Montana, August 26, 1999.