80-969



Base from Texas Department of Highways and Public Transportation

FIGURE 7.-Land-surface subsidence in subregion 4, 1918-51 and 1942-75