9 A



9 B

9C



9D



9 E

Figure 9A. Thermal imagery showing icing near Globe Creek Crossing

Figure 9B. Oblique photograph made in June 1974 showing residual ice.

Figure 9C. Frame photograph of area surrounding site.

Figure 9D. Example of strip photography with too much uncompensated roll to be useful for interpretation.

Figure 9E. Livengood 1-3 topographic map.