80-969



Base from Texas Department of Highways and Public Transportation

FIGURE 8.-Land-surface subsidence in subregion 5, 1917-51