

Base from Texas Department of Highways and Public Transportation General Highway Map

Figure 18.-Changes in water levels in wells completed in the Chicot aquifer caused by a leaking gas well