

Figure 40. Selected Indicators of Thermal Maturation.

[Sample Sources: A–Cuttings, B–Sidewall Cores, C–Conventional Cores]