PRELIMINARY GEOLOGIC MAP OF THE THISTLE LANDSLIDE, UTAH COUNTY, UTAH

By
R.W. Fleming[1], B.N. Kaiser[2], I.J. Witkind[1] and D.E. Fair[3]
September, 1985

[1] U.S. Geological Survey, Box 25046, Federal Center, Denver, CO, 80225
[2] Utah Geological and Mineral Survey, 606 Black Hawk Way, Salt Lake City, UT, 84108-1280
[3] Consultant (Kaiser Engineers Group, 4177 Hudson Street, Arvada Ridge, CO, 80033)

EXPLANATION

INTRINSIC TO THISTLE LANDSLIDE

- Scarp
- Thrust fault — Sawteeth on upper plate
- Fracture — Bar and ball rest on downthrown block
- Lobate toe of earthflow — Arrows indicate direction of movement
- Upwarp
- Base of scarp
- Tension crack
- Shear zone (Distributed strike-slip movement)
- Shear fracture (Strike-slip fault)

Q(TKn) — Debris of the Thistle Landslide derived chiefly from the North Horn Formation (TKn).

TKn — North Horn Formation

UNCONFORMITY

JTrn — Nugget Sandstone (Now known as the Navajo Sandstone)

Tea — Ankareh Formation

CONTACT — Approximately located or inferred; dotted where concealed.

14/ — Strike and dip of inclined beds

DH-4 — DRILL HOLE. Approximately located. Holes drilled by Rhodes Brothers under supervision of Northern Engineering and Testing Inc., North Salt Lake City, Utah, 84054.

SH-2 — DRILL HOLE. "Stats drill hole." Drilled under supervision of Woodward-Clyde Consultants.

RB&G-2 — DRILL HOLE. Drilled under supervision of Robins Brown and Gendell Inc., 1675 West 820 North, Provo, Utah, 84601.

Thistle Point 6008.4

Sill 5045

Intake 5170

Outlet 5008

Spanish Fork River

Old Highway 6 & 91

Scale 1:2,400

Contour interval 20 ft

NOTE: Topography prepared from aerial photography of August, 1984 (below 5670 ft.) and May, 1983 (above 5670 ft.)

N 609600 N 608800 N 608000 N 607200 N 606400 N 605600 N 604800 N 604000

E 1994400 E 1995200 E 1996000 E 1996800 E 1997600 E 1998400 E 1999200 E 2000000 E 2000800 E 2001600 E 2002400 E 2003200

PLATE 2