83-4026



Base from U.S. Geological Survey topographic quadrangles

Figure 6.–Distribution of hydraulic conductivity in fresh-water aquifer in the Truscott area