ERRATA SHEET

WRIR 86-4358 PLATE 3

HYDROGEOLOGY OF STRATIFIED-DRIFT AQUIFERS AND WATER QUALITY IN THE NASHUA REGIONAL PLANNING COMMISSION AREA
SOUTH-CENTRAL NEW HAMPSHIRE

ERROR	TOWN	NEAREST LANDMARK	CORRECTION
1	Amherst	State Route 101/Lincoln Pond area	Flow arrows on water-table contours 260,270, opposite direction
2	Amherst	Merrimack Road/Nichols Road junction	Water-table contour 200 should be 220
3	Merrimack	Naticook Brook southwest of Thorntons Ferry	Flow arrow on water-table contour 170, opposite direction
4	Merrimack	Southeast of Duck Pond	Flow arrows on water-table contours 190, 200, opposite direction