ERRATA SHEET

WRIR 86-4358 PLATE 3

HYDROGEOLOGY OF STRATIFIED-DRIFT AQUIFERS AND WATER QUALITY IN THE NASHUA REGIONAL PLANNING COMMISSION AREA
SOUTH-CENTRAL NEW HAMPSHIRE

ERROR	TOWN	NEAREST LANDMARK	CORRECTION
5	Amherst	Boston Post Road/ Souhegan River area	Water-table contour 230 should be 200
6	Hollis	Silver Lake	Flow arrow on water-table contour 270, opposite direction
7	Nashua	Cold Brook, southwest Nashua	Water-table contour 190 should be 170