ERRATA SHEET

WRIR 86-4358 PLATE 4

HYDROGEOLOGY OF STRATIFIED-DRIFT AQUIFERS AND WATER QUALITY IN THE NASHUA REGIONAL PLANNING COMMISSION AREA
SOUTH-CENTRAL NEW HAMPSHIRE

ERROR	TOWN	NEAREST LANDMARK	CORRECTION
3	Merrimack	Lawrence Corner/Souhegan River area	Saturated thickness contours 20, 40, 60, should be 10, 20 40.
4	Merrimack	Lawrence Corner/Souhegan River area	Saturated thickness contour 40 should be 10
5	Nashua	FE Everett Turnpike/Rivier College area	Saturated thickness contours 40, 60, should be 10, 20