


EXPLANATION

- SAND AND GRAVEL
- GLACIAL DEPOSITS
- SIYEH LIMESTONE
- LIMESTONE TALUS
- 30° STRIKE AND DIP OF BEDS
- 52° B BEDDING FAULT
- 42° T REVERSE FAULT
- 66° NORMAL FAULT
- PTBM 3106 PLANE-TABLE BENCH MARK
- .30' DEPTH OF WATER OCT. 2 1935
- A — A' LINE OF CROSS SECTION
- APPROXIMATE LIMITS OF PREGLACIAL CHANNEL
- ③ LOCALITY NUMBER

# GEOLOGIC MAP OF CORAM CANYON DAM SITE

SOUTH CENTER SECTION 5, T. 30 N., R. 19 W.
FLATHEAD COUNTY, MONTANA

0 200 400 800 1200 FEET

CONTOUR INTERVAL 50'
*DATUM IS MEAN SEA LEVEL*

GEOLOGY BY C.E. ERDMANN 1935

725605 O - 47 (In pocket)