

EXPLANATION

Foot of Bonneville bench

Foot of Provo bench

Area of artesian flow, 1931–33

Edge of flowing well area in 1904, by G. B. Richardson in U.S. Geological Survey Water-Supply Paper 157

Successful well drilled by Salt Lake City Corporation during 1934

Unsuccessful well drilled by Salt Lake City Corporation during 1934

Foot of mountains

MAP OF JORDAN VALLEY, SALT LAKE COUNTY, UTAH, SHOWING THE POSITION OF THE BONNEVILLE AND PROVO BENCHES, AREA OF ARTESIAN FLOW, 1931-33, AND LOCATION OF WELLS DRILLED BY SALT LAKE CITY CORPORATION DURING 1934

827626 O - 49 (In pocket) No. 2