UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

WATER-SUPPLY PAPER 1607
PLATE 5

EXPLANATION

Fault

1000
900

Structure contours drawn on the fire-clay coal

Contour interval 100 feet northwest of the Pine Mountain thrust fault, 1000 feet southeast of the thrust fault.

Datum is mean sea level



Modified from McFarlan, 1950

STRUCTURE MAP OF THE EASTERN COAL FIELD REGION, KENTUCKY

10 0 10 20 MILES