






- EXPLANATION**
-  Shear zones and faults, showing dip
 -  Vertical fault
 -  Quartz vein, showing dip
 -  Stoped area
 -  Foot of raise or winze
 -  Head of raise or winze
 -  Ore chute
 -  Caved workings



MAP SHOWING WORKINGS OF THE FERN MINE

