


94 CCT 01

6/27/94 - 6/30/94

6/27/94 (Calt TX, W. LA)



Note - changed to this →
on 6/30

Part Gen

STS Hydropho (2V deep cycle batt.)

Hunter PS. /slid (low power: 6 simles)

Delph 2 V1.22

Geolink XDS (Gulf. 61m background map)

Oyo plotter

M/o drive / 1 Gb hard drive (Delph sys)

(data saved on hard drive transferred to M/o)

EFI UIS (2) - one for monitor/oyo printer

- one for hard drive / m/o drive / computer

DELPH NAV DRIVER - NAV_LX (11/92) (Renamed NAV1192.EXE on 5/96)

Sabine Pass (Jack)

6/27/94

SOL NAV627-1. * - nav line 10:20

SOL SL627-1. DAT - seismic line

SOL 10:28 fix 14

fix 19 pause increase port 60 to 135 jibs

fix 20 continue

fix 240 - 14:07

EOL

SOL - SL627-2 14:19 fix 252 of NAV627-1

- fix set + 10 sec interval

shot 170000 aground } to clear bent board
shot 176000 clear }

EOL SL627-2. - 15:35

EOL NAV627-1. - gen trouble due to clogs after aground

L.I.

SOL SL627-3. * 16:09 - using starboard gen - seems OK

SOL NAV627-2. *

EOL SL627-3 - shot 137000 fix 330 (marker 34)

SOL SL627-4 17:43 fix 551

EOL SL627-4 17:54 fix 615 shot 700

EOL NAV627-2 18:04

6/28/94 starboard gen Sabine lake
- 60 sec position

SOL SL628-5 (seismic) 07:54 - start roll 3
SOL NAV628-3 (NAV)

EOL SL628-5 fix 56, 8:48

SOL SL628-6 fix 58 8:49

EOL SL628-6 fix 228 11:21

EOL NAV628-3 11:35

NOTE - NAV file inadvertently overwritten by sensor NAV628-3

SOL NAV628-3 (NAV) 12:27 - fix every 10 sec

SOL SL628-7 (seismic) 12:29 in Backwater Bayou fix 14

EOL SL628-7 13:09 fix 283

SOL SL628-8 13:35 fix 397 channel fun

EOL SL628-8 13:41 fix 474

SOL SL628-9 15:13 fix 964

EOL SL628-9 15:37 fix 1001

fix 1722 shot 7750 - printer halted (

fix 1767 shot 8800 - plotting resume

SOL SL628-10 fix 1533 16:51 in the bayou
fix 1722, shot 7750 - plotter halted
for some reason
fix 1767, shot 8800 - plotting resumed
EOL SL628-10 fix 2105, shot 22500
EOL NAV628-3 18:35

6/29/94 Sabin Lake

SOL NAV629-4 07:30

SOL SL629-11 Fix 3

EOL SL629-11 9:04, Fix 93 shot 2150

SOL SL629-12 9:08 Fix 97
Fix 258 turn

Dog Leg ^{Fix} # 258 1639:57
turn - back towards East

Fix 281 - now every 10 sec

EOL SL629-12 10:15, Fix 364

SOL SL629-13 12:16, Fix 362

EOL SL629-13 15:46, Fix 692

SOL TST 15:44, Fix 699 - hydrophore, sled on same side
(starboard)

EOL TST Fix 732

EOL NAV629-4 4:55

WMM

6/30/94

Sabine Lake

now in internet - port gen in use
(battery swapped)


SOL SL630-14 7:06

SOL NAV630-4 7:07

fix 41-46 - new partitions held

fix 100 - sled moved back 10 meters

EOL fix 104



SOL SL630-15

0:921 fix 123

fix 211 turn south

fix 248 turn east, shot 29300

EOL SL630-15

fix 327 12:44

SOL SL630-16

12:58 fix 345-

fix 347 - turn west again

NOTE: New towing config eliminates ship rolls (sled 10m back)

- flat seas 6/30 "

EOL SL630-16

14:49, fix 455

SOL GM630-17

16:11

fix 538

- Gulf of Mex

EOL GM630-17

16:20

576