

|                    |                              |                  |                  |                 |
|--------------------|------------------------------|------------------|------------------|-----------------|
| Div. No.<br>W73164 | Title<br>HA508 M WABASH R IN | Series<br>HA-508 | Date<br>12-20-72 | Sheet<br>7 of 7 |
|--------------------|------------------------------|------------------|------------------|-----------------|

| Description                                 | Sym-bols      | PMS PROCESS    |       |
|---|---------------|----------------|-------|
|   |               | BLUE           | BLACK |
| Red Area                                    |               | 1              |       |
| Blue Area                                   |               | 5              |       |
| MAP SHOWING SPECIFIC COND., DRAIN. AREAS,?? |               |                |       |
| Specific conductance range, in micromhos    | less than 500 | 7              |       |
|   | 500-600       | 5              |       |
|   | 600-700       | 1              |       |
|   | 700-800       | 214<br>// 135° |       |
|   | more than 800 | 214<br>// 45°  |       |
|   | not determ.   | BLANK          |       |
| Drainage Boundary                           |               | <u>.010</u>    |       |
| Basin Boundary                              |               | — • • —        |       |

BASE SCREENED  
BLACK (49)

