



A-A' SECTION THROUGH FOGARTY SHAFT AREA, FOGARTY AND BUCK MINES


B-B' SECTION THROUGH WORKINGS OF THE BUCK MINE





C-C' SECTION THROUGH WORKINGS OF THE YOUNGS AND BALTIC MINES



D-D' SECTION THROUGH WORKINGS OF THE ZIMMERMAN MINE



E-E' SECTION THROUGH DEGRASSE SHAFT AND EASTERN WORKINGS OF ZIMMERMAN AND BUCK MINES



LOCATION OF CROSS SECTIONS IN SECS. 1 AND 12, T. 42 N., R. 35 W., AND SECS. 6 AND 7, T. 42 N., R. 34 W.