

## 13-3 FHA

**STAMPING** 13-3 1986  
**USGS QUAD MAP** SYLVAN LAKE (1991)  
**NGS PID** PY0896

**LATITUDE** 44.49680  
**LONGITUDE** -110.19733  
**ELEVATION** 2612 m

---

### **DATE OF DESCRIPTION** 2008

**DESCRIPTION** Proceed 23.2 km (14.40 mi) southeast along the East Entrance Highway from its junction with the Canyon-Lake highway (just west of Fishing Bridge). Bench mark is in a large grassy park, 24.4 m (80.1 ft) northeast of the centerline of the highway, 4.0 m above the highway, and 0.5 m south-southeast from a witness post. From the bench mark it is 78.5 ft at N04W to a 12" lodgepole pine and 84.9 ft at N34E to a 4" lodgepole pine.

In 2003 and 2008, the bench mark was searched for and not found. The FHA description is probably correct. The bench mark is in a meadow on the outside of a sharp bend in the highway (on the east side of road). The 12-inch and 4-inch trees referenced in FHA description are present, but after measuring distances from trees and probing in the tall grass, nothing was found. The fence post referenced in the FHA description is missing. If the mark is still present, it is buried under meadow duff and will require a metal detector to find.



Photograph of the two trees referenced in the FHA description and approximate location of mark (orange vest).



Looking northeast at meadow and probable location of bench mark. Trees referenced in the FHA description are in the left-middle ground.