

13-5 FHA

STAMPING
USGS QUAD MAP
NGS PID

LATITUDE
LONGITUDE
ELEVATION

DATE OF DESCRIPTION 2008

DESCRIPTION Proceed 28.24 mi southeast along the East Entrance highway from its junction with the Canyon-Lake highway (just west of Fishing Bridge). Bench mark is about 23 ft south of the centerline of the highway, opposite Buffalo Bills Lodge, 2.0 mi east of the east entrance Yellowstone National Park, set in a concrete monument, and marked by a metal fence post 2.2 ft to the east. From the mark it is 17.0 ft at S13W to a 4" lodgepole pine and 58.2 ft E to a 10" lodgepole pine.

In 2008 the bench mark was searched for and not found, presumed destroyed. The bench mark is opposite Buffalo Bill's Camp/Lodge, in an area which now has 4 paved highway lanes. The FHA description places the bench mark under pavement, so it is presumed to have been destroyed by roadwork.