

## 39 MDC (1976)

**STAMPING** 39 MDC 1976 8437  
**USGS QUAD MAP** SYLVAN LAKE (1991)  
**NGS PID** PY0899

**LATITUDE** 44.48940  
**LONGITUDE** -110.17705  
**ELEVATION** 2580 m

---

**DATE OF DESCRIPTION** 2008

**DESCRIPTION** Proceed 25.7 km (15.95 mi) southeast along the East Entrance Highway from its junction with the Canyon-Lake highway (just west of Fishing Bridge). Bench mark is near the west end of a highway pullout, 13.1 m (43.0 ft) south of the centerline of the highway, 0.6 m (2.0 ft) north of a 30-inch fir tree, encased in a pipe flush with the ground, and 1.0 m below the highway.

In 2003 and 2008 the bench mark was searched for and not found. The pullout referenced in the NGS description exists, and candidates for the 30-inch fir tree referenced in the NGS description exist at about the right location as charred stumps. Road fill has buried the north bases of the stumps by about 2 feet, so the bench mark (which is described as 2 feet north of 30-inch fir) is likely buried as well too.



Looking east at probable location of bench mark.  
Stump of 30-inch tree in NGS description is in the lower right of photo, partly buried by road fill.