



Base modified from U.S. Geological Survey Digital Raster Graphics for Barceloneta, Manatí, Florida, and Ciales, 1:25,000. Elevation from U.S. Geological Survey, National Elevation Dataset (NED). Lambert conformal conic projection, Puerto Rico Datum, 1940 Adjustment. Flood area delineated from hydraulic model results using the U.S. Army Corps of Engineers, Hydrologic Engineer Center's River Analysis System (HEC-RAS).

Any use of trade, product, or firm names in this publication is for descriptive purposes only and does not imply endorsement by the U.S. Government. Digital files available at <http://pubs.usgs.gov/sir/2015/5065/>. Suggested citation: Torres-Sierra, Heriberto, and Gómez-Fragoso, Julieta, 2015, Dam failure analysis for the Matanzas Dam, Orocuiva, Puerto Rico, U.S. Geological Survey Scientific Investigations Report 2015-5065, 54 p., 4 pls., <http://dx.doi.org/10.3133/SI5065>, ISSN 2288-0228 (online).

Sunny Day Conditions

By
Heriberto Torres-Sierra and Julieta Gómez-Fragoso
2015