



Figure 2.— Plan of sublevels and stopes near the northeast end of 5<sup>th</sup>, 6<sup>th</sup>, and 7<sup>th</sup> levels, Scrub Oaks mine, Morris County, New Jersey

30 20 10 0 30 60 FEET