

Figure 6.--Discharge hydrograph for Beaver Creek (site 1) at Huntingdon, Tenn. (see table 2 for site description).





Figure 7.--Discharge hydrograph for Middle Fork Forked Deer River Tributary (site 9) at **Humboldt**, Tenn. (see table 2 for site description.)




Figure 8.--Flooded residential area in Trenton, Tenn.



Figure 9.--Flooded business area along U.S. Highway 45W in Trenton, Tenn.



Figure 10.--Approximate flood boundaries of North Fork Forked Deer River along U.S. Highway 45W Bypass and State Route 77 at Trenton, Tenn.



Figure 11.--Approximate flood boundaries of Rutherford Fork Obion River along U.S. Highway 70A & 79 between Milan and Atwood, Tenn.



Figure 12.--Approximate flood boundaries of Rutherford Fork Obion River along U.S. Highway 45E between Milan and Bradford, Tenn.

CLARENCE H. ROBBINS, CHARLES R. GAMBLE and R. H. BINGHAM