ERRATA SHEET

WRIR 86-4358 PLATE 4

HYDROGEOLOGY OF STRATIFIED-DRIFT AQUIFERS AND WATER QUALITY IN THE NASHUA REGIONAL PLANNING COMMISSION AREA SOUTH-CENTRAL NEW HAMPSHIRE

CORRECTION ERROR **NEAREST LANDMARK** Saturated thickness contour 10 should be 60 and contours 20,40 Souhegan River/East Milford boundary Amherst have been added. Saturated thickness, transmissivity, and materials missing from base. Data included on copy below. Amherst Souhegan River/East Milford boundary AMHERST 0 lford Milford Milford

ERRATA SHEET

WRIR 86-4358 PLATE 2

HYDROGEOLOGY OF STRATIFIED-DRIFT AQUIFERS AND WATER QUALITY IN THE NASHUA REGIONAL PLANNING COMMISSION AREA SOUTH-CENTRAL NEW HAMPSHIRE

ERROR	TOWN	NEAREST	LANDMARK			CORRECTION		
1 Broo	okline	State Route	130 near Hollis t	own line	Saturated thick	kness contour 40 sh	hould be 10	
	SPACE IN		Middle Mill //	11/19	1:///: Y	=- 1 // - 1	// 100	IIIE 3 INC. INC.
*	211		Pond .		(O) - 5	- 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	900	TRE
3/10/1			(130)	111			105 770111	(E) ((I) (I) (E) ((I) (I) (E) ((I) (I) (I) (I) ((I) (
- U/2	TAN	PO FRANK	PEP	PERELL	1 1		10 /6 /5/10	SKIIIIIIII
	1	NOT X		218			3 (0 SUN)	
MAN		000		5000				(924)
	6	- Carlo	Bohannon	- R. V. TH		1/2000	JAN LUBE	
300			6 22 J	impoeds	8	2/2007/18	10	
5====	112	J OP		tradow.		SUPPLIE	Sign	
O Tank	South	Brookline &	The same	San Jan	20 77:			3
12		(//0//)	0.0	TANK			21 20	
	((())	100011112	1.00	6 11/2		00		
	- BF	ROOKL	INE A	Charles Andrews		A. A. Company	95	
					1			
	1000	1/1/=	1.0	2011		A SET H	5/16/	TESTE!
300	in Const	300	1) ? (1 3 3	13/1 TO //	1
Pierge	V	21/1/2	S S	1/0)			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	\$ \$ 000 CE
Poma	1	SIED	000	(000)		The state of the s	West Hollis	7-1-1
5((((68)	NEW HAN	ADCHIDE			-1- N		1	The same
501119	06	APSHIKE	59	Alt ====================================		17	10.00	1 = 1