UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SE¼ OF GOULD PASS 15' QUADRANGLE
NEW MEXICO-SAN JUAN-RIO ARRIBA COS.

OPEN FILE REPORT 79-615
PLATE 8 OF 12



EXPLANATION

0
5

ISOPACHS OF THE FRUITLAND 3 COAL BED - Showing thickness, in feet. Isopach interval 5 feet (1.5 meters).

O7

DRILL HOLE - Showing thickness of the Fruitland 3 coal bed, in feet.

To convert feet to meters, multiply feet by 0.3048.

Fruitland coal beds contoured as a single surface on this map are equivelent in stretigraphic position but may not be continuous.

Base from U.S. Geological Survey, 1959

SCALE 1:24000

1 MILE
1000 0 1000 2000 3000 4000 5000 6000 7000 FEET
1 KILOMETER

Compiled in 1979

COAL RESOURCE OCCURRENCE MAP OF THE SOUTHEAST QUARTER OF THE GOULD PASS 15-MINUTE QUADRANGLE, RIO ARRIBA AND SAN JUAN COUNTIES, NEW MEXICO

BY
DAMES & MOORE
1979

This map was prepared under contract to the U.S. Geological Survey and has not been edited for conformity with Geological Survey editorial standards. Opinions and conclusions expressed herein do not necessarily represent those of the Geological Survey.

PLATE 8
ISOPACH MAP OF THE
FRUITLAND 3 COAL BED