U.S. DEPARTMENT OF THE INTERIOR
U.S. GEOLOGICAL SURVEY

PREPARED IN COOPERATION WITH THE
U.S. DEPARTMENT OF ENERGY

Plate 1
OFR 96-417

SCR–T1



SCR–T3



North walls compiled by photogrammetric methods from close-range photographs (Fairer and others, 1988; Coe and others, 1991), taken November 1992 and June 1993.

Orthographic Projection Planes:
SCR-T1: Vertical plane striking S65E E with an origin at
939401.8 E and 727131.0 N (Nevada State Plane Coordinate System)
SCR-T3: Vertical plane striking S65E E with an origin at
936518.7 E and 716551.8 N (Nevada State Plane Coordinate System)

South walls logged using conventional techniques of manual gridding and plotting in July—August 1993. The south wall logs were digitized, then presented in mirrored image as if viewed from the south.

Survey control by Raytheon Services, Nevada.

Photographs by Johnson Control



(NOT TO SCALE)

EXPLANATION

- **Contact between lithologic units**—Dashed where approximate
- **Fracture or shear**—Dashed where approximate, queried where uncertain
- **Surface rupture tectonic boundary**—Fissure or buried scarp-free face
- **Soil horizon boundary**—Lithologic contacts take precedence over soil horizons where the two coincide
- **Combined lithologic contact/soil-horizon boundary**—Dashed where approximate
- **Calcium carbonate stringer**
- **Krotovina**
- **Selected clasts**
- **Selected rhizoliths and root casts carbonate cemented**—Dashed where approximate
- A A / A' A' **Match line for subdivision of large-scale logs (Plates 2 and 3)**

LOG OF PART OF THE NORTH AND SOUTH WALLS OF TRENCHES SCR–T1 AND SCR–T3, STAGECOACH ROAD FAULT, SOUTHEAST EDGE OF YUCCA MOUNTAIN, NYE COUNTY, NEVADA

C.M. Menges, J.A. Oswald, J.A. Coe, and M. Murray

1997