



INDEX MAP SHOWING THE RELATIVE LOCATION OF THE STAYTON AND YELLOW JACKET MINES

100 0 100 Feet



SKETCH A

0 1 Foot



SECTION A-A'

EXPLANATION

80° Cinnabar veins, showing dip

58° Strike and dip of fault

Inclined workings (Chevrons point downward with vertical interval between them of about 2 feet)

Country rock is basalt.

GEOLOGIC MAP AND SECTION OF THE UPPER LEVELS OF THE STAYTON MINE, MERCED COUNTY, CALIFORNIA

25 0 100 Feet