U.S. GEOLOGICAL SURVEY 12/30/53 LIBRARY (200) E



SECTION ALONG LINE A-A'



INCLINED LONGITUDINAL SECTION ALONG BASE OF ORE "BED"



EXPLANATION

Ore "bed," Santa Teresa adit

Ore "bed," San Roque adit

Ore "bed," Español No. 2 adit

60 — Fault, showing dip
Dashed where approximately located. With 1-3 cm. gouge

90 — Vertical fault

35 — Strike and dip of foliation

•8m. — Elevation in meters, above Español Antiguo portal

Brunton-tape survey by Q. D. Singewald

PLAN AND SECTIONS OF THE LOWER ADITS, QUINDIO MINE, MUNICIPIO OF CAJAMARCA, TOLIMA, COLOMBIA

864306 O - 50 (In pocket)