
USGS
science for a changing world
Digital Map of Recently Active Traces of the Hayward Fault, California
30
31
32
33
Keller Ave
Leona Quarry
Interstate 580
Mountain Bl
Fontaine St
Golf Links Rd
Arroyo Viejo
73rd Ave
82nd Ave
T,H2,A2341
G3,sl
G2,lv
G2,sl,gi
G3,sl,gi
G3,hb,mp
G3,sl
C2,C2,rc,so,so
C2,rc,cs
G2,sl
T,H2,E06
G3,sl
C3,ra?,ls?,M98
C2,u,G94
C2,u,G94
C2,ec
G2,hv
N
0
0.25
0.5
Miles
Kilometers
0
0.5
1