
N 40° W
S 60° E
N 60° W
S 76° E
N 76° W
S 89° E
CLIFF FAULT
BASE of STILLWATER COMPLEX
LITTLE EAST FAULT
DIKE
FAULT
LAKE FAULT
LAKE FAULT and DIKE
LAKE FAULT in DDH #28
(Hole proj. South along strike of Lagers 150' to this section)
Mouat Nickel Mine
D.D.H.NO.E
D.D.H.NO.A
D.D.H.NO.B
SECTION E - E'
to accompany
GEOLOGIC MAP OF MOUNTAIN VIEW LAKE AREA
scale 1/1200