U.S. GEOLOGICAL SURVEY

PREPARED IN COOPERATION WITH THE SAN BERNARDINO COUNTY FLOOD CONTROL DISTRICT

FIGURE 5

(200)
M814an



EXPLANATION

UNCONSOLIDATED DEPOSITS

CONSOLIDATED ROCK

FAULT – Dashed where approximately located, dotted where concealed

700 WATER-LEVEL CONTOUR – Shows altitude of water level. Contour interval, in feet, as shown. Datum is mean sea level

U.S. GEOLOGICAL SURVEY
WASHINGTON
MAR 6 1973
LIBRARY

Base compiled from California Department of Water Resources and San Bernardino County Flood Control District

0 3 6 MILES

WATER-LEVEL ALTITUDE, 1969, IN THE UPPER SANTA ANA VALLEY, SOUTHERN CALIFORNIA

FIGURE 6



EXPLANATION

UNCONSOLIDATED DEPOSITS

CONSOLIDATED ROCK

FAULT – Dashed where approximately located, dotted where concealed

300 LINE OF EQUAL DEPTH TO WATER BELOW LAND SURFACE – Interval, in feet, as shown

Base compiled from California Department of Water Resources and San Bernardino County Flood Control District

0 3 6 MILES

DEPTH TO WATER, 1969, IN THE UPPER SANTA ANA VALLEY, SOUTHERN CALIFORNIA