

Appendix I. Interpretation of electric log of oil test hole, showing lignite beds and formational boundaries. Davis Oil Company 1 Andy, NW¼NW¼ Sec. 7, T. 5 S., R. 63 W.