74-258

U. S. Geological Survey
OPEN-FILE REPORT
This report is preliminary and has not been edited or reviewed for conformity with Geological Survey standards or nomenclature.



Figure 5 Histograms showing estimated modes of significant minerals in different batholiths plutons, and igneous rock units, southern half of Zone III, Santander - Norte de Santander Colombia.