UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SW¼ OF LLAVES 15′ QUADRANGLE
NEW MEXICO-SAN JUAN CO.

OPEN FILE REPORT 79-608

PLATE 10 OF 12



Base from U.S. Geological Survey, 1955

Compiled in 1979

SCALE 1:24 000

1 ½ 0 1 MILE

1000 0 1000 2000 3000 4000 5000 6000 7000 FEET

1 .5 0 1 KILOMETER

EXPLANATION

3000

OVERBURDEN ISOPACHS - Showing thickness of overburden, in feet, from the surface to the top of the Fruitland 2 coal bed. Isopach interval 400 feet (122 meters). Isopachs dashed where inferred. Supplemental 3000-foot (914-meter) overburden isopach added.

○ 2913

DRILL HOLE - Showing thickness of overburden, in feet, from the surface to the top of the Fruitland 2 coal bed.

To convert feet to meters, multiply feet by 0.3048.

COAL RESOURCE OCCURRENCE MAP OF THE SOUTHWEST QUARTER OF THE LLAVES 15-MINUTE QUADRANGLE, RIO ARRIBA COUNTY, NEW MEXICO

BY
DAMES & MOORE
1979

This map was prepared under contract to the U.S. Geological Survey and has not been edited for conformity with Geological Survey editorial standards. Opinions and conclusions expressed herein do not necessarily represent those of the Geological Survey.

PLATE 10

ISOPACH MAP OF OVERBURDEN OF THE FRUITLAND 2 COAL BED