UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

KIN NAHZIN RUINS QUADRANGLE
NEW MEXICO—MC KINLEY CO.
7.5 MINUTE SERIES (TOPOGRAPHIC)

OPEN FILE REPORT 79-639
PLATE 15 OF 19



This report has not been edited for conformity with Geological Survey editorial standards or stratigraphic nomenclature.

EXPLANATION

900

OVERBURDEN ISOPACHS-Showing thickness of overburden, in feet, from the surface to the top of the Menefee Cleary No. 1 coal bed. Isopach interval 100 feet. Isopachs dashed where inferred. o793

DRILL HOLE-Showing thickness of overburden, in feet, from the surface to top of the Menefee Cleary No. 1 coal bed.

To convert feet to meters, multiply feet by 0.3048.

COAL RESOURCE OCCURRENCE MAP OF THE KIN NAHZIN RUINS QUADRANGLE, McKINLEY COUNTY, NEW MEXICO

BY

BERGE EXPLORATION, INC.

1979

PLATE 15

ISOPACH MAP OF OVERBURDEN OF THE MENEFEE CLEARY NO.1 COAL BED