UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

OPEN FILE REPORT 79 - 804

PLATE 3 OF 28

This map was prepared under contract to the U.S. Geological Survey and has not been edited for conformity with Geological Survey editorial standards. Opinions and conclusions expressed herein do not necessarily represent those of the Geological Survey.

COAL RESOURCE OCCURRENCE MAP OF THE PINE PILLAR QUADRANGLE, SAN JUAN COUNTY, NEW MEXICO

BY

DAMES & MOORE

1979

CORRELATION OF COAL BEDS IN DRILL HOLES



Compiled in 1979

PLATE 3
SHEET 2 OF 2

COAL DATA SHEET