UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SAN LUIS QUADRANGLE
NEW MEXICO-SANDOVAL COUNTY
7.5 MINUTE SERIES (TOPOGRAPHIC)

OPEN FILE REPORT 79-1044
PLATE 13 OF 21

This report has not been edited for conformity with Geological Survey editorial standards or stratigraphic nomenclature.



EXPLANATION

ISOPACHS OF THE MENEFEE CLEARY NO. 1 COAL BED-Showing thickness in feet. Isopach interval 1 foot (0.3 meter). Isopachs dashed where inferred.

DRILL HOLE-Showing thickness of the Menefee Cleary No. 1 coal bed in feet.

TRACE OF COAL BED OUTCROP-Showing coal thickness, in feet, measured at triangle. Arrow points toward the coal-bearing area. Dashed line indicates inferred outcrop.

FAULT-Dashed where approximately located; bar and bell on downthrown side.

To convert feet to meters, multiply feet by 0.3048.

APPROXIMATE MEAN DECLINATION, 1961

SCALE 1:24000

NEW MEXICO
QUADRANGLE LOCATION

COAL RESOURCE OCCURRENCE MAP OF THE SAN LUIS QUADRANGLE, SANDOVAL COUNTY, NEW MEXICO

BY

BERGE EXPLORATION, INC.

1979

PLATE 13
ISOPACH MAP OF THE
MENEFEE CLEARY NO.1
COAL BED