UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NW¼ OF AZTEC 15' QUADRANGLE
NEW MEXICO-SAN JUAN CO.

OPEN FILE REPORT 79-1112
PLATE 10 OF 20



Base from U.S. Geological Survey, 1959

SCALE 1:24 000

1 ½ 0 1 MILE

1000 0 1000 2000 3000 4000 5000 6000 7000 FEET

1 .5 0 1 KILOMETER

Compiled in 1979

EXPLANATION

2600

OVERBURDEN ISOPACHS - Showing thickness of overburden, in feet, from the surface to the top of the Fruitland 2 coal bed. Isopach interval 200 feet (61 meters). Isopachs long dashed where inferred, short dashed where projected through noncoal-bearing area.

○ 2469

DRILL HOLE - Showing thickness of overburden, in feet, from the surface to the top of the Fruitland 2 coal bed.

To convert feet to meters, multiply feet by 0.3048.

COAL RESOURCE OCCURRENCE MAP OF THE NORTHWEST QUARTER OF THE AZTEC 15-MINUTE QUADRANGLE, SAN JUAN COUNTY, NEW MEXICO

BY
DAMES & MOORE
1979

This map was prepared under contract to the U.S. Geological Survey and has not been edited for conformity with Geological Survey editorial standards. Opinions and conclusions expressed herein do not necessarily represent those of the Geological Survey.

PLATE 10

ISOPACH MAP OF OVERBURDEN OF THE FRUITLAND 2 COAL BED