UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

PINE RIVER QUADRANGLE
NEW MEXICO
7.5 MINUTE SERIES (TOPOGRAPHIC)

OPEN FILE REPORT 79-1120
PLATE 13 OF 31



Base from U.S. Geological Survey, 1954 (Photorevised 1971)

Compiled in 1979



UTM GRID AND 1971 MAGNETIC NORTH DECLINATION AT CENTER OF SHEET

SCALE 1:24 000

QUADRANGLE LOCATION

EXPLANATION

2800

OVERBURDEN ISOPACHS - Showing thickness of overburden, in feet, from the surface to the top of the Fruitland 3 coal bed. Isopach interval 200 feet (61 meters). Isopachs dashed where projected through noncoal-bearing area.

O 2848

DRILL HOLE - Showing thickness of overburden, in feet, from the surface to the top of the Fruitland 3 coal bed.

To convert feet to meters, multiply feet by 0.3048.

COAL RESOURCE OCCURRENCE MAP OF THE PINE RIVER QUADRANGLE, RIO ARRIBA AND SAN JUAN COUNTIES, NEW MEXICO

BY
DAMES & MOORE
1979

This map was prepared under contract to the U.S. Geological Survey and has not been edited for conformity with Geological Survey editorial standards. Opinions and conclusions expressed herein do not necessarily represent those of the Geological Survey.

PLATE 13
ISOPACH MAP OF OVERBURDEN
OF THE FRUITLAND 3 COAL BED